

Re: Hanford mixed waste trench (landfill) groundwater monitoring plan 🗎

Dave Bartus to: Sheila Fleming

06/27/2012 02:19 PM

Does this mean we get to do filtered groundwater sampling?

Dave

Sheila Fleming Clear as mud. I'll get back to you:) Sheila 06/27/2012 01:44:06 PM

From: Sheila Fleming/R10/USEPA/US
To: Dave Bartus/R10/USEPA/US@EPA,

Date: 06/27/2012 01:44 PM

Subject: Re: Hanford mixed waste trench (landfill) groundwater monitoring plan

Clear as mud. I'll get back to you:)

Sheila

Sheila Fleming, P.E.

Risk Evaluation Unit Manager U.S. Environmental Protection Agency Office of Environmental Assessment 1200 Sixth Avenue, Suite 900, M/S OEA-095 Seattle, Washington 98101

Office: 206.553-1417 Mobile: 206.303.8126

Dave Bartus Sheila: Please find attached the "current" plan. ... 06/27/2012 01:39:05 PM

From: Dave Bartus/R10/USEPA/US

To: Sheila Fleming/R10/USEPA/US@EPA,
Cc: Lisa McArthur/R10/USEPA/US@EPA

Date: 06/27/2012 01:39 PM

Subject: Hanford mixed waste trench (landfill) groundwater monitoring plan

Sheila:

Please find attached the "current" plan. Not to get buried in the weeds, this plan is based on monitoring a large expanse of unlined trenches, which EPA generally takes the position are not even subject to RCRA (or authorized state dangerous waste) groundwater monitoring requirements. The two mixed waste trenches that are the subject of my inquiry aren't even identified in the Plan (could this be a problem?) - the two mixed waste trenches/landfills are actually located in the far southern tip of the 218-W-5 burial ground.

Dave

[attachment "LLBG_Trenches_31_and_34_ADD_D_Groundwater_Combo.pdf" deleted by Sheila Fleming/R10/USEPA/US]